




DRILLING TEMPLATE



ATTENTION: The maximum torque exerted on the steering wheel bolts must be between 3 and 5 Nm. Over-tightening may result in thread damage.

Please print this page in 1:1 scale (100%).